



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Hugh, Allen_2_21129035470000

MGRRE

Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Hugh, Allen_2_21129035470000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 7952.

<https://scholarworks.wmich.edu/pure/7952>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Hugh, Allen_2_21129035470000

API 21129035470000

Permit Number 3547

Lease Name Hugh, Allen

Well Number 2

County Ogemaw

Township 22N

Range 02E

Section 20

2021 DEQ or Pure co_name Bachelder and Gallaher

Pure Number 257

Latitude 44.28123

Longitude -84.2128


Form 216-F WELL REPORT - OUTSIDE OPERATIONS

SERIAL NO. 257STATE Michigan ~~PSH~~ Ogemaw CO.OPERATOR Bachelor & CallaherFARM Hugh Allen WELL NO. 2TWP. West Branch S. 20 T. 22N R. 2ELOC. SE NW SEWILDCAT ☐ FIELD ☐ FIELD NAME _____

MAP NO. _____ CO-ORD. _____ ELEV. _____

STATUS Plugged and Abandoned 3-11-48Total Depth 2727'

NORTH

DATE 4-12-48 SCOUT H. J. G.

THE PURE OIL COMPANY
LOCATION REPORT

Date November 25, 1946

A.F.E. No. _____

Division Mich. Producing District _____ Lease Hugh Allen

Acres _____ Lease No. _____ Elevation _____ Well No. 2 (Serial No. 257)

Quadrangle SE NW SE Sec. 20 Twp. 22 N Rge. 2 E ~~SW~~ ~~NE~~ Twp. West Branch

Survey _____ County Ogemaw State Michigan

Operator Bachelder & Gallaher Map West Branch Township, Ogemaw County

Feet from North Line of Lease

" " East " " "

" " South " " "

" " West " " "

Feet from North Line of Section


" " East " " "

" " South " " "


" " West " " "


LEGEND


○ Location


 Gas Well


● Oil Well



 Gas - Distillate Well



○ or  Dry Hole



 Dry Showing Oil

 Dry Showing Gas


 Abandoned Location

 or  Abandoned Gas Well

 or  Abandoned Oil Well

 or  Input Well

See plat - Ogemaw #257.



Remarks: Change of operator. Scale _____

Submitted by Scouting Dept. ~~CHODEN~~ Approved by _____ Division Manager

Approved by _____ Vice-President - General Manager

DATE September 17, 1936

LOCATION REPORT

No. 257STATE Michigan

COUNTY

Ogemaw

DIST.

West Branch

SEC.

20

TOWN

22 N

RANGE

2 EWELL No. 2(SERIAL No. 257)

FARM

PREC.

Hugh Allen

ACRES

NAME OF STREAM OR WATERS

QUADRANGLE

SE-NW-SE
SE NW SE

OPERATOR

Durham and Jones

Map

West Branch Township, Ogemaw CountyDurham & JonesWest Branch - Oge Co.

Feet from North Line of Farm

515 515

" " East " " "

200 300

" " South " " "

" " West " " "

1120 1120

Feet from North Line of Section

" " East " " "

" " South " " "

805 805" " West " 1 1/4 "Only 40'

LEGEND

O LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

⬮ SMALL OIL WELL

⊙ DRY HOLE

⬮ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

☼ ABANDONED GAS WELL

⬮ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

R. L. Ysaga

Superintendent or Foreman.

